MATERIAL SAFETY DATA SHEET



4700 W. 160TH Street P.O. Box 35906 Cleveland, Ohio 44135 Emergency Tel No. (303) 623-5716 Collect

OATEY 95/5 ROSIN CORE WIRE SOLDER

test Revision Date...06/06/00 Date of Issue.....04/11/05 Section 1 IDENTITY OF MATERIAL TRADE NAME..... OATEY 95/5 ROSIN CORE WIRE SOLDER PRODUCT NUMBERS... 53171, 53173, 53175, 53177 FORMULA..... 95/5 SYNONYMS..... 95/5 Rosin Core Solder SECTION 2 HAZARDOUS INGREDIENTS INGREDIENTS CAS NUMBER SEC 313 Tin <95% 7440-31-5 No Antimony < 5% 7440-36-0 Yes ER99 Core (RA Type) Non-Hazardous < 1% N/A No =========== SECTION KNOWN HAZARDS UNDER 29 CFR 1910.1200 HAZARDS YES NO HAZARDS YES <u>NO</u> Combustible Liquid Skin Hazard x Flammable Material x Eye Hazard x Pyrophoric Material x Toxic Agent Explosive Material Highly Toxic Agent x Unstable Material Sensitizer х Water Reactive Material x Kidney Toxin Oxidizer Reproductive Toxin x × Organic Peroxide Blood Toxin Corrosive Material Nervous System Toxin x Compressed Gas Lung Toxin Irritant Liver Toxin Carcinogen NTP/IARC/OSHA x SECTION 4 REGULATION HEMICAL TLV (TWA) PEL STEL Hazard Action Level I'in (Inorganic) 2.0 mg/cu m 2.0 mg/cu m N/A N/A Antimony 0.5 mg/cu m 0.5 mg/cu m N/A N/A ===== ________ --------------------------SECTION 5 REGULATED IDENTIFICATION DOT PROPER SHIPPING NAME..... N/A DOT HAZARD CLASS..... N/A SHIPPING ID NUMBER..... N/A EPA HAZARDOUS WASTE ID NUMBER... N/A EPA HAZARD WASTE CLASS..... N/A SECTION 6 EFFECTS OF EXPOSURE ENTRY ROUTE.... INHALE - YES INGEST - YES SKIN - YES EYE - YES INHALATION..... If heated, fumes may produce respiratory irritation, fever, chills, muscular pain, vomiting, dizziness, sweating, and a metallic taste in mouth. Overexposure to fumes can cause a flu-like condition called Metal Fume Fever. Overexposure to antimony fumes has been reported to cause heart irregularities. SKIN..... Fumes may cause irritation. EYE..... Fumes may cause irritation. INGESTION...... May cause abdominal pain, nausea, vomiting, diarrhea, gastrointestinitis, internal cuts or obstructions. TARGET ORGANS... Lung, Skin, Eye irritant by heated fumes, kidneys, liver, and heart. CALIFORNIA..... Formaldehyde Warning: Use of this product exposes the user to formaldehyde, a chemical known to the State STATE LAW of California to cause cancer. PROPOSITION 65 ==== SECTION 7 EMERGENCY AND FIRST AID PROCEDURES - 303/623-5716 COLLECT SKIN...... If irritation arises, wash thoroughly with soap and water. Seek medical attention if irritation persists. EYES...... If fumes cause irritation, move to fresh air and irrigate eyes with water for 15 minutes. If irritation persists, seek medical attention. If eye is struck with wire, seek medical attention. INHALATION... Move to fresh air. If breathing is difficult, give oxygen. If not breathing, give artificial respiration.

Keep victim quiet and warm. Call a poison control center or physician immediately.

anything by mouth to an unconscious person.

NGESTION.... Drink water and call a poison control center or physician immediately. Avoid alcoholic beverages. Never give

(Continued on next page)

OATEY 95/5 ROSIN CORE WIRE SOLDER

SECTION 8 PHYSICAL AND CHEMICAL PROPERTIES NFPA HAZARD SIGNAL..... HEALTH - 1 FLAMMABILITY - 0 STABILITY - 0 SPECIAL - NONE BOILING POINT...... N/A MELTING POINT..... 240 Degrees C -- 464 Degrees F VAPOR PRESSURE..... N/A VAPOR DENSITY (AIR = 1) ... N/A VOLATILE COMPONENTS..... N/A SOLUBILITY IN WATER..... Insoluble PH..... N/A SPECIFIC GRAVITY..... 9 - 11 EVAPORATION RATE..... N/A APPEARANCE..... Silver-Gray Wire Metal ODOR..... None WILL DISSOLVE IN..... N/A MATERIAL IS..... Solid SECTION 9 FIRE AND EXPLOSION HAZARD DATA FLAMMABILITY..... LEL = N/A UEL = N/AFLASHPOINT AND METHOD USED..... N/A STABILITY...... Stable. CONDITIONS TO AVOID: N/A HAZARDOUS DECOMPOSITION PRODUCTS: Metal fumes above melting point. HAZARDOUS POLYMERIZATION...... Will not occur. MATERIALS TO AVOID: None INCOMPATIBILITY/MAT. TO AVOID..... Strong oxidizers, acids, potassium and halogen gases SPECIAL FIRE FIGHTING PROCEDURE... FOR SMALL FIRES: Use dry chemical, CO(2), water or foam extinguisher. FOR LARGE FIRES: Evacuate area and call fire department immediately. SECTION 10 SPILL AND DISPOSAL INFORMATION SPILL OR LEAK PROCEDURES... Place material in a closed container. WASTE DISPOSAL..... According to local, state and federal regulations. SECTION SAFE USAGE DATA PROTECTIVE EQUIPMENT TYPES... EYES: Safety glasses with side shields. RESPIRATORY: NIOSH-approved respirator for toxic dust/fumes. GLOVES: Rubber OTHER: None VENTILATION...... GENERAL MECHANICAL: Necessary if soldering in non-ventilated area. LOCAL EXHAUST: Open doors and windows to remove fumes. PRECAUTIONS...... HANDLING AND STORAGE: Practice good personal hygiene and housekeeping.

SECTION 12

______ MANUFACTURER OR SUPPLIER DATA

FIRM NAME & MAILING ADDRESS... OATEY CO., 4700 WEST 160TH STREET, P.O. Box 35906, CLEVELAND, OHIO 44135

OATEY PHONE NUMBER..... (216) 267-7100

EMERGENCY PHONE NUMBER:..... (303)-623-5716 COLLECT

SECTION 13

DISCLAIMER

The information herein has been compiled from sources believed to be reliable, up-to-date, and is accurate to the best of our knowledge. However, Oatey cannot give any guarantees regarding information from other sources, and expressly does not make warranties, nor assumes any liability for its use.